

TZ 300

Assembly of lever press



The illustration shows the device and the GUNT Media Center on a tablet (not included).

Description

- GUNT course: engineering drawing
- lever press as assembly kit
- multimedia instructional materials online in GUNT Media Center: 3D PDF, DXF files, STEP files, video

A drawing is the most important means of information and communication in engineering. The ability to read and understand drawings, graphics and schematics is a fundamental element in the development of professional competence in all engineering disciplines. Linking engineering communication to the associated technical operations such as assembly structure, work plans and manufacturing is just as important.

The TZ 300 assembly kit is an interdisciplinary and practical project. In addition to the primary learning area of "engineering drawing", it is also possible to deal with the topics of machine elements, assembly processes and in particular production engineering. The assembly kit includes all single parts required to assemble a functional lever press. The parts are clearly displayed on a base plate.

The contemporary multimedia instructional materials are available online in the GUNT Media Center. The core element of the teaching materials is a complete set of drawings as files with list of parts, single-part drawings, exploded views, assembly drawings and 3D drawings. All drawings are to standard and are dimensioned in accordance with production requirements. The set of drawings consists of DXF files, STEP files and PDF files. The assembly video is also a useful feature.

The manufactured parts are precision-manufactured from original materials and with common tolerances and surfaces. The surfaces of the manufactured parts are burnished to prevent corrosion. All parts are clearly laid out and well protected in a storage system. Multiple storage systems can be stacked on top of each other, allowing space-saving storage.


Learning objectives/experiments

- introduction to engineering drawing
 - read and understand engineering drawings
 - ▶ three-dimensional display
 - ▶ sectional views
 - ▶ drawing types
 - ▶ 3D representation
 - ▶ lists of parts
 - ▶ dimensioning
 - ▶ surface and tolerance specifications
- difference between standard and production parts
- ▶ materials specifications
- planning and execution of simple assembly operations
 - ▶ plan and describe operations
 - ▶ evaluate results
- measuring exercises
 - ▶ longitudinal measurements
- ▶ angular measurements
- manufacturing processes
- working examples of handmade production and production on machine tools



TZ 300

Assembly of lever press



1 base plate, 2 foot, 3 stand, 4 arch, 5 compression spring, 6 pressure pin, 7 fork, 8 handle



Screenshot of the GUNT Media Center



Functional groups of the lever press: fork, pressure pin, main body

Specification

- [1] part of the GUNT course on engineering drawing
- [2] assembly kit of a functional lever press
- [3] all production parts of the lever press made from steel, precision-manufactured, burnished surfaces
- [4] storage system for parts
- [5] multiple storage systems can be stacked on top of each other
- [6] instructional material incorporates action-oriented and interdisciplinary forms of teaching
- [7] multimedia instructional materials: PDF, CAD files, STEP files, videos
- [8] online access to the GUNT Media Center

Technical data

LxWxH: 420x300x70mm (storage system) Weight: approx. 3kg

Scope of delivery

- storage system with the individual parts of the lever press
- 1 set of tools for assembly and disassembly
- 1 set of small parts
- 1 set of instructional material