


P.O. Box 377 03012 Vilnius, Lithuania Phone: +370-5-2651474 Fax: +370-5-2651483 E-mail: sales@standa.lt http://www.standa.lt

## Prism / Optics Mount with two fine adjustment screws

#### 5PM131M-2






P.O. Box 377 03012 Vilnius, Lithuania Phone: +370-5-2651474 Fax: +370-5-2651483 E-mail: sales@standa.lt http://www.stande.lt

### Prism / Optics Mount with 3 fine adjustment screws

#### 5PM131M-3






P.O. Box 377 03012 Vilnius, Lithuania Phone: +370-5-2651474 Fax: +370-5-2651483 E-mail: sales@standa.lt http://www.standa.lt

# Prism / Optics Mount with two fine adjustment screws

#### 5PM131-2



2 holes

M4x4 deep

6 holes



P.O. Box 377 03012 Vilnius, Lithuania Phone: +370-5-2651474 Fax: +370-5-2651483 E-mail: sales@standa.lt http://www.standa.lt

### Prism / Optics Mount with 3 fine adjustment screws

5PM131-3

